

Figure E.29 Time Step of Surface Corrosion for 0.0% Chloride Pre-Cracked Specimens




Figure E.30 Time Step of Rib Loss for 0.0% Chloride Pre-Cracked Specimens